Type	#	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	다 다 아 아
BRS	디	Н	computer and ((smart adj card) same fan same air)	USPA T	2003/12/1 9 09:36			0
BRS	1.2	184	computer and ((card) same fan same air)	USPA T	2003/12/1 9 09:35			0
BRS	L3	10	computer and ((card) same fan same air)	JPO	2003/12/1 9 09:35			0
BRS	L4	2	computer and ((smart adj card) same fan same air )	US-P GPUB ; EPO; JPO; DERW. ENT; IBM	2003/12/1 9 09:37			0

	Туре	# I	Hits	Search Text	DBs	Time C Stamp	Comment	Error Definition	Er ro rs
7	BRS	L1	322	chip) damp\$4)	USPA T	2003/12/1 9 10:26			0
2	BRS	1.2	24	(processor or chip) and (fan same damp\$4)	JPO	2003/12/1 9 10:26			0
m	BRS	L3	8	(processor or chip) and (fan same vibration)	JPO	2003/12/1 9 10:28			0
4	BRS	<u>L</u> 4	22	(processor or chip) and (fan same vibration)		2003/12/1 9 10:30			0
5	BRS	LS	<b>†</b>		EPO; DERW ENT; IBM TDB	2003/12/1 9 10:32			0
9	BRS	T6	293	computer and (fan same vibration)	USPA T	2003/12/1 9 10:40			0
7	BRS	L7	276		USPA T	2003/12/1 9 10:32			0
8	BRS	L8	83	computer and (fan same washer\$1)	USPA T	2003/12/1 9 10:42			0
თ	BRS	F19	2	computer and (fan same washer\$1)	JPO	2003/12/1 9 10:43			0
10	BRS	L10	1 1 1	computer and (fan same washer\$1)	EPO; DERW ENT; IBM_ TDB_	2003/12/1 9 10:43			0